



10/709451

cofc

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of

DEVINE et al.

Atty. Ref.: 839-1306

Patent No. 7,296,615

Issued: November 20, 2007

For: METHOD AND APPARATUS FOR DETERMINING THE
LOCATION OF CORE-GENERATED FEATURES IN AN
INVESTMENT CASTING

* * * * *

December 21, 2007

Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

Sir:

REQUEST FOR A CERTIFICATE OF CORRECTION

The patentee in the above-identified patent hereby requests that the Patent and Trademark Office issue an official Certificate of Correction pursuant to 37 C.F.R. § 1.322 for the following error made by the Patent Office.

Column 5, line 4 (see Examiners Amendment i.e. Notice Of Allowability) after the word "forming" the phrase "said datum pad or pads having" is missing.

Column 5, line 7, (Examiners Amendment) after the word "said" the phrase "one or more datum pads are located on portions of the core print-out that extend outside of said internal cavity and said" is missing.

DEC 28 2007

Column 5 lines 15 and 16 (Examiners Amendment) after the word "pads" the phrase "are located on portions of the core print-out that extend outside of said external cavity and" should not appear.

Since the error arose on the part of the Patent and Trademark Office, no fee is believed necessary for securing issuance of the Certificate.

Attached hereto is a draft Official Certificate of Correction for use by the Patent and Trademark Office correcting the above-identified matter.

The Commissioner is hereby authorized to charge any deficiency in the fee(s) filed, or asserted to be filed, or which should have been filed herewith (or with any paper hereafter filed in this application by this firm) to our **Account No. 14-1140**. A duplicate copy of this sheet is attached.

Respectfully submitted,

NIXON & VANDERHYE P.C.

By: 
William G. Niessen
Reg. No. 29,683

WGN:rlg
901 North Glebe Road, 11th Floor
Arlington, VA 22203-1808
Telephone: (703) 816-4000
Facsimile: (703) 816-4100

DEC 28 2007

Staple
Here
Only!

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO. : 7,296,615
DATED : November 20, 2007
INVENTOR(S) : DEVINE et al.

It is certified that error appears in the above-identified patent and that said letters patent is hereby corrected as shown below:

At column 5 line 4 after the word "forming" insert the phrase "said datum pad or pads having"

At column 5 line 7 after the "said" insert the phrase "one or more datum pads are located on portions of the core print-out that extend outside of said internal cavity and said"

At column 5 lines 15-16 after the word "pads" delete the phrase "are located on portions of the core print-out that extend outside of said external cavity and"

MAILING ADDRESS OF SENDER:

William G. Niessen
NIXON & VANDERHYE P.C.
901 North Glebe Road, 11th Floor
Arlington, Virginia 22201

PATENT NO. 7,296,615

No. of add'l
@ 50¢ per page

Form PTO 1050 (Rev. 2-93)

DEC 28 2007

Staple
Here
Only!

COPY

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO. : 7,296,615
DATED : November 20, 2007
INVENTOR(S) : DEVINE et al.

It is certified that error appears in the above-identified patent and that said letters patent is hereby corrected as shown below:

At column 5 line 4 after the word "forming" insert the phrase "said datum pad or pads having"

At column 5 line 7 after the "said" insert the phrase "one or more datum pads are located on portions of the core print-out that extend outside of said internal cavity and said"

At column 5 lines 15-16 after the word "pads" delete the phrase "are located on portions of the core print-out that extend outside of said external cavity and"

MAILING ADDRESS OF SENDER:

William G. Niessen
NIXON & VANDERHYE P.C.
901 North Glebe Road, 11th Floor
Arlington, Virginia 22201

PATENT NO. 7,296,615

No. of add'l.
© 50¢ per page

Form PTO 1050 (Rev. 2-93)

DEC 28 2007